

#### **OCCUPATION CERTIFICATE**

Pursuant to Part 6 of the Environmental Planning & Assessment Act 1979

CERTIFICATE No.: OC-21139
DETERMINATION: Approved

**DATE OF DETERMINATION:** 20 December 2021

SUBJECT LAND:

Lot & DP Lot 11 DP 1178389
Address 2 Aldington Road, Kemps Creek NSW 2178

LOCAL GOVERNMENT AREA: Penrith City Council

APPLICANT:

Name Ben Milner

Company Goodman Property Services (Aust) Pty Ltd

Address Level 17, 60 Castlereagh Street, Sydney NSW 2178

Phone: 02 9230 7120 Email: Ben.milner@goodman.com

OWNER:

Name BGMG 11 Pty Ltd

Address Level 17, 60 Castlereagh Street, Sydney NSW 2178

Phone / Fax / Email Phone: 02 9230 7120 Email: Ben.milner@goodman.com

**DESCRIPTION OF DEVELOPMENT:** Stage 2 development including construction, fit-out, operation and use of a four-level

automated warehouse, associated office space, internal roads and parking.

Note: This Occupation Certificate excludes any external ancillary services, structures or civil

works required by relevant authorities.

WHOLE / PART: Part – Four-Level Automated Warehouse, excluding the Level 3 (P4) automation

equipment fitout and the operation of the P4 AR field.

BCA CLASSIFICATION: Class 5 & 7b

**DEVELOPMENT CONSENT:** 

Development Application No. & Date of

Determination

SSD 10397 (09.04.2020), MOD 1 (23.09.2020) & MOD 2 (04.05.2021)

CONSTRUCTION CERTIFICATE:

Construction Certificate No. & Date of

Determination

CC-20105 (28.05.2020), CC-20130 (30.06.2020), CC-20139 (14.07.2020), CC-20161 (16.10.2020), CC-21003 (02.02.2021), CC-21003/A (31.08.2021) & CC-21003/B (25.11.2021).

#### **STATUTORY CERTIFICATION:**

Blackett Maguire + Goldsmith certify that:

- + The health and safety of the occupants of the building have been taken into consideration where an **interim/part** Occupation Certificate is being issued; and
- + A current development consent or complying development certificate is in force for the building; and
- + If any building work has been carried out, a current construction certificate (or complying development certificate) has been issued with respect to the plans and specifications for the building; and
- + The building is suitable for occupation or use in accordance with its classification under the Building Code of Australia; and
- A fire safety certificate has been issued for the building (if required); and
- A report from the Fire Commissioner has been considered (if required).

DOCUMENTATION RELIED UPON:

**DETAILS OF CERTIFYING AUTHORITY:** 

Certifying Authority Accreditation No. As listed in Schedule 1

Blackett Maguire + Goldsmith Pty Ltd

RBC00004

SIGNATURE:

SIGNED ON BEHALF OF BM+G:

Dean Goldsmith

Date: 20/12/2021

Accreditation No. BDC 0141



# SCHEDULE 1

## SCHEDULE OF DOCUMENTATION

## **DOCUMENTATION RELIED UPON**

The following documentation was relied upon in issuing this Occupation Certificate:

#### + Documentation:

ITEM	DOCUMENTATION	PREPARED BY	DATE
1.	OC Application Form	Goodman Property Services (Aust) PL	08.11.2021
2.	Final Fire Safety Certificate	Goodman Property Services (Aust) PL	18.12.2021
3.	Engineering Certificate of Inspection	Penrith City Council	26.06.2020
4.	Section 73 Compliance Certificate	Sydney Water Corporation	10.08.2021
5.	Certificate of Practical Completion	NBN	08.07.2021
6.	Fire Assessment Report No. FAS210098 – fire performance of steel beams and columns	Warringtonfire	29.07.2021
7.	Fire Safety Certification – Lightweight construction	Bowsers	17.08.2021
8.	Global Assessment Report P104585-1072 – fire performance of steel air ducts	BRE	27.05.2021
9.	Fire Assessment Report No. FAS 190202 – fire resistance performance of various pipes and cables	Warringtonfire	14.02.2020
10.	Fire Assessment Report No. FAR 4236 – fire resistance of a steel stud beam	Branz	26.06.2014
11.	Fire Assessment Report No. 45821 – Promaseal A Acrylic sealant	Warringtonfire	03.04.2020
12.	Fire Assessment Report No. FAS 190145 – fire resistance performance of I-Section Steel Beams	Warringtonfire	02.08.2019
13.	Certification of Installed System – Certificate no. 3555 – height safety	Proactive Safety PL	05.10.2021
14.	Certificate of Test No. FNR12814C - CSIRO	CSIRO	28.09.2021
15.	Fire Testing Report No. FNR12814 – prefinished structural particle board	CSIRO	26.10.2021
16.	Secretary's Certificate – Satisfactory Arrangements – Public Infrastructure	Planning, Industry & Environment	16.08.2019
17.	Secretary's Certificate – Satisfactory Arrangements – Public Infrastructure	Planning, Industry & Environment	19.04.2020
18.	Secretary's Certificate – Satisfactory Arrangements – Public Infrastructure	Planning, Industry & Environment	09.04.2020
19.	Test Report No. M0930b - Slip resistance - pedestrian	Slip Check	08.07.2020
20.	Project Waratah Contact List	Not Specified	Not Dated
21.	Email correspondence regarding contributions (not payable)	Goodman Property Services (Aust) PL	26.07.2021
22.	Structural Engineering Certificate – Vanderlande Conveyor Supports	David Beneke Consulting	24.06.2021
23.	Structural Engineering Certificate – Vanderlande conveyor supports	David Beneke Consulting	22.11.2021
24.	Vanderlande ESA Fire Requirements Plan	Maxwell J McDonald	01.03.2021



26. Email confirming receipt of post approval documentation – DA#A10b  27. Compliance Monitoring Reporting Program Operations  28. Email confirming receipt of post approval documentation – DA#A10b  29. Design Certificate – Conveyor Support Abbot Design (Aust) PL  29. Design Certificate – Conveyor Support Abbot Design (Aust) PL  29. Design Certificate – Conveyor Support Abbot Design (Aust) PL  29. Design Certificate – Conveyor Support Platforms  30. Statement of Compliance – Conveyor Support Platforms and Balustrades  31. Initial Electrical Installation Certificate  32. Amended Electrical Installation Certificate  33. Certificate of Test No. FNR12815C – CSIRO  34. Fire Testing Report No. FNR12815 – structural particle board  35. Architectural Design Compliance Statement  36. Structural Construction Certificate  37. Structural Construction Certificate  38. Installation Certificate – Electrical  39. Installation Certificate – Hydraulic  40. Hinstallation Certificate – Electrical  40. Hinstallation Certificate – Schedule of fire hazard properties – carpet and vinyl)  40. + Product Data Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous Vinyl Sheet  4 Test Report No. 19-004615  4 Homogeneous V				
Email confirming receipt of post approval documentation – DA#A10b   S. Environment   S. E	Ітем	DOCUMENTATION	PREPARED BY	DATE
documentation - DA#A10b   & Environment	25.	Installation Certificate – Outdoor lighting	New Edge Group PL	25.11.2021
Coperations   Email confirming receipt of post approval documentation — DA#C14   & Environment   22.09   Segment   Certificate — Conveyor Support   Abbot Design (Aust) PL   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03   01.03	26.			16.08.2021
documentation – DA#C14  29. Design Certificate – Conveyor Support Platforms  30. Statement of Compliance – Conveyor Support Platforms and Balustrades  31. Initial Electrical Installation Certificate  32. Amended Electrical Installation Certificate  33. Certificate of Test No. FNR12815C – Mezzanine Antislip  34. Fire Testing Report No. FNR12815 – structural particle board  35. Architectural Design Compliance Statement  36. Structural Construction Certificate  37. Structural Construction Certificate  38. Installation Certificate – Costin Roe Consulting PL  39. Installation Certificate – Electrical  40. Hallation Certificate – Hydraulic  40. Hallation Certificate (schedule of fire hazard properties – carpet and vinyl)  41. Certificate of Test No. FNR11455C  42. Product Data Sheet  43. Honogeneous Vinyl Sheet  44. External Wall system Disclosure Certificate  43. Statement – Glue to insulated panel  44. External Wall system Disclosure Certificate  45. Test Report No. 16-002279 – colourbond steel  46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly  47. System Specifications – Steel Frame Internal Wall Systems  48. Installation Certificate – Schedule of Lightweight Fire Rated Construction  49. Installation Certificate – Schedule of Lightweight Fire Rated Construction  49. Installation Certificate – Schedule of Lightweight Fire Rated Construction  50. Architectural Performance Solution Report  51. Installation Certificate – Warning & Operational signs	27.		SLR	21.09.2021
Platforms  30. Statement of Compliance – Conveyor Support Platforms and Balustrades  31. Initial Electrical Installation Certificate Vanderlande 10.11  32. Amended Electrical Installation Certificate Vanderlande 22.11  33. Certificate of Test No. FNR12815C – Mezzanine Antislip  34. Fire Testing Report No. FNR12815 – structural particle board 25.11  35. Architectural Design Compliance Statement SBA Architects PL 26.11  36. Structural Construction Certificate Costin Roe Consulting PL 22.09  37. Structural Construction Certificate Costin Roe Consulting PL 22.09  38. Installation Certificate – Electrical New Edge Group PL 25.11  39. Installation Certificate (schedule of fire hazard properties – carpet and vinyl) + Certificate of Test No. FNR11455C Regupol AWTA Product Testing 13.08  + Product Data Sheet Arms Arms Arms Arms Arms Arms Arms Arms	28.			22.09.2021
Platforms and Balustrades  31. Initial Electrical Installation Certificate  32. Amended Electrical Installation Certificate  33. Certificate of Test No. FNR12815C – Mezzanine Antislip  34. Fire Testing Report No. FNR12815 – structural particle board  35. Architectural Design Compliance Statement  36. Structural Construction Certificate  37. Structural Construction Certificate  38. Installation Certificate – Electrical  39. Installation Certificate – Hydraulic  40. H Installation Certificate (Schedule of fire hazard properties – carpet and vinyl)  40. + Certificate of Test No. FNR11455C  4 Product Data Sheet  4 Test Report No. 19-004615  4 H Homogeneous Vinyl Sheet  4 Test Report No. 7-666333-AN  4 Building Blocks – loop pile  41. Certificate of Test No. FNC11629 – stone wool  42. Reaction-to-fire test report no. RTF190172 – low carbon steel  43. Statement – Glue to insulated panel  44. External Wall system Disclosure Certificate  45. Test Report No. 16-002279 – colourbond steel  46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly  47. System Specifications – Steel Frame Internal  Wall Systems  48. Installation Certificate – Schedule of Inner Part Interiors  19.09  51. Installation Certificate – Warning & Operational signs  New Edge Group PL  26.10  26.11  26.11  26.11  26.11  26.11  26.11  26.11  27. Armstrong Flooring Commercial  27. Amrstrong Flooring Commercial  28. AwTA Product Testing  29. AwTA Pr	29.	1 , , , , , , , , , , , , , , , , , , ,	Abbot Design (Aust) PL	01.03.2021
32.       Amended Electrical Installation Certificate       Vanderlande       22.11         33.       Certificate of Test No. FNR12815C – Mezzanine Antistip       CSIRO       30.09         34.       Fire Testing Report No. FNR12815 – structural particle board       CSIRO       26.10         35.       Architectural Design Compliance Statement       SBA Architects PL       26.11         36.       Structural Construction Certificate       Costin Roe Consulting PL       22.09         37.       Structural Construction Certificate       New Edge Group PL       22.11         38.       Installation Certificate – Electrical       New Edge Group PL       25.11         39.       Installation Certificate – Hydraulic       Central Plumbing Contracting PL       26.11         40.       + Installation Certificate (schedule of fire hazard properties – carpet and vinyl)       Sydney Bass Floor       25.11         41.       Certificate of Test No. FNR11455C       Regupol       AWTA Product Testing       25.10         42.       Fest Report No. 7-566333-AN       Interface       19.08         43.       Statement – Glue to insulated panel       ASKIN Engineering       04.02         42.       Reaction-to-fire test report no. RTF190172 – low carbon steel       Skyivew Roffing       24.11         45.       Test R	30.	Statement of Compliance – Conveyor Support Platforms and Balustrades	Abbot Design (Aust) PL	28.10.2021
33. Certificate of Test No. FNR12815C - Mezzanine Antislip  34. Fire Testing Report No. FNR12815 – structural particle board  35. Architectural Design Compliance Statement  36. Structural Construction Certificate  37. Structural Construction Certificate  38. Installation Certificate – Electrical  39. Installation Certificate – Hydraulic  40. Hastallation Certificate (Schedule of fire hazard properties – carpet and vinyl)  40. + Certificate of Test No. FNR11455C  40. + Product Data Sheet  41. Certificate of Test No. FNR11455C  42. Reaction-to-fire test report no. RTF190172 – low carbon steel  41. Certificate of Test No. FNC11629 – stone wool  42. Reaction-to-fire test report no. RTF190172 – low carbon steel  43. Statement – Glue to insulated panel  44. External Wall system Disclosure Certificate  45. Test Report No. 16-002279 – colourbond steel  46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly  47. System Specifications – Steel Frame Internal Wall Systems  48. Installation Certificate – Schedule of Lightweight Fire Rated Construction  51. Installation Certificate – Warning & Operational signs  30.09  30.09  30.09  40.02  41. Certificate of Test No. FNR12815 – structural Costin Roe Consulting PL  42. Reaction-to-fire test report no. RTF190172 – low carbon steel  43. Statement – Glue to insulated panel  44. External Wall system Disclosure Certificate  45. Test Report No. 16-002279 – colourbond steel  46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly  47. System Specifications – Steel Frame Internal Wall Systems  48. Installation Certificate – Schedule of Lightweight Fire Rated Construction  49. Installation Certificate – Fire Seals  40. Architectural Performance Solution Report  51. Installation Certificate – Warning & Operational ligns	31.	Initial Electrical Installation Certificate	Vanderlande	10.11.2021
Mezzanine Antislip  34. Fire Testing Report No. FNR12815 – structural particle board  35. Architectural Design Compliance Statement  36. Structural Construction Certificate  37. Structural Construction Certificate  38. Installation Certificate – Electrical  39. Installation Certificate – Hydraulic  40. Hinstallation Certificate (schedule of fire hazard properties – carpet and vinyl)  40. + Certificate of Test No. FNR11455C  41. Product Data Sheet  42. Hongeneous Vinyl Sheet  43. Building Blocks – loop pile  41. Certificate of Test No. FNC11629 – stone wool  42. Reaction-to-fire test report no. RTF190172 – low carbon steel  43. Statement – Glue to insulated panel  44. External Wall system Disclosure Certificate  45. Test Report No. 16-002279 – colourbond steel  46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly  47. System Specifications – Steel Frame Internal Wall Systems  48. Installation Certificate – Schedule of Lightweight Fire Rated Construction  51. Installation Certificate – Warning & Operational ligns  49. Installation Certificate – Warning & Operational ligns	32.	Amended Electrical Installation Certificate	Vanderlande	22.11.2021
35. Architectural Design Compliance Statement SBA Architects PL 26.11 36. Structural Construction Certificate Costin Roe Consulting PL 22.09 37. Structural Construction Certificate Costin Roe Consulting PL 22.09 38. Installation Certificate - Electrical New Edge Group PL 25.11 39. Installation Certificate (schedule of fire hazard properties - Carpet and vinyl) + Certificate of Test No. FNR11455C + Product Data Sheet Abroad - Test Report No. 19-004615 + Homogeneous Vinyl Sheet + Test Report No. 7-566333-AN + Building Blocks - loop pile  41. Certificate of Test No. FNR11629 - stone wool CSIRO 4.02 42. Reaction-to-fire test report no. RTF190172 - low carbon steel 43. Statement - Glue to insulated panel ASKIN Engineering 04.04 44. External Wall system Disclosure Certificate Skyview Roofing 24.11 45. Test Report No. 16-002279 - colourbond steel AWTA Product Testing 10.05 46. Fire Assessment Report No. FC11160-001 - duct and fire damper assembly Not Specified Not Specified Not Systems Specifications - Steel Frame Internal Wall Systems Installation Certificate - Schedule of Lightweight Fire Rated Construction 19.09 51. Installation Certificate - Warning & Operational signs New Edge Group PL 25.11	33.		CSIRO	30.09.2021
36.Structural Construction CertificateCostin Roe Consulting PL22.0937.Structural Construction CertificateCostin Roe Consulting PL22.0938.Installation Certificate – ElectricalNew Edge Group PL25.1139.Installation Certificate – HydraulicCentral Plumbing Contracting PL26.1140.+ Installation Certificate (schedule of fire hazard properties – carpet and vinyl)Sydney Bass Floor25.1141 Certificate of Test No. FNR11455CRegupol13.08+ Product Data SheetAWTA Product Testing25.10+ Test Report No. 19-004615Armstrong Flooring CommercialApril 2+ Homogeneous Vinyl SheetAWTA Product Testing13.05+ Test Report No. 7-566333-ANInterface19.0841.Certificate of Test No. FNC11629 – stone woolCSIRO04.0242.Reaction-to-fire test report no. RTF190172 – low carbon steelWarringtonfire06.0843.Statement – Glue to insulated panelASKIN Engineering04.0444.External Wall system Disclosure CertificateSkyview Roofing24.1145.Test Report No. 16-002279 – colourbond steelAWTA Product Testing10.0546.Fire Assessment Report No. FC11160-001 – duct and fire damper assemblyBranz10.0147.System Specifications – Steel Frame Internal Wall SystemsNot SpecifiedNot Specified48.Installation Certificate – Schedule of Lightweight Fire Rated ConstructionInner Part Interiors03.1249.Insta	34.		CSIRO	26.10.2021
37.       Structural Construction Certificate       Costin Roe Consulting PL       22.09         38.       Installation Certificate – Electrical       New Edge Group PL       25.11         39.       Installation Certificate – Hydraulic       Central Plumbing Contracting PL       26.11         40.       + Installation Certificate (schedule of fire hazard properties – carpet and vinyl)       Sydney Bass Floor       25.11         40.       + Certificate of Test No. FNR11455C       Regupol       21.09         40.       + Test Report No. 19-004615       Armstrong Flooring Commercial       April 2         40.       + Test Report No. 19-004615       Armstrong Flooring Commercial       April 2         40.       + Test Report No. 7-566333-AN       Interface       13.05         41.       Certificate of Test No. FNC11629 – stone wool       CSIRO       04.02         42.       Reaction-to-fire test report no. RTF190172 – low carbon steel       Warringtonfire       06.08         43.       Statement – Glue to insulated panel       ASKIN Engineering       04.04         44.       External Wall system Disclosure Certificate       Skyview Roofing       24.11         45.       Test Report No. 16-002279 – colourbond steel       AWTA Product Testing       10.05         46.       Fire Assessment Report No. FC11160-001	35.	Architectural Design Compliance Statement	SBA Architects PL	26.11.2021
38. Installation Certificate – Electrical New Edge Group PL 25.11 39. Installation Certificate – Hydraulic Central Plumbing Contracting PL 26.11 40. + Installation Certificate (schedule of fire hazard properties – carpet and vinyl) + Certificate of Test No. FNR11455C Regupol Product Data Sheet AWTA Product Testing AWTA Product Testing AWTA Product Testing AWTA Product Testing 13.05 AWTA Product Testing 15.05 AWTA Product Testing 15.05 Interface Plus Report No. 7-566333-AN Building Blocks – loop pile Warringtonfire Warringtonfire 16.08 Skyview Roofing 16.08 Skyview Roofing 16.08 Skyview Roofing 16.08 Skyview Roofing 16.05 Fire Assessment Report No. FC11160-001 – duct and fire damper assembly Wall Systems Specifications – Steel Frame Internal Wall Systems Installation Certificate – Schedule of Lightweight Fire Rated Construction 16.0 Architectural Performance Solution Report SBA Architects PL 90.09.09 Share Fire Assessing Report No. Republic Report No. Regupol 25.11 Signs Specificate – Warning & Operational signs New Edge Group PL 25.11 Signs Specificate – Warning & Operational signs New Edge Group PL 25.11 Signs Specificate – Warning & Operational signs New Edge Group PL 25.11	36.	Structural Construction Certificate	Costin Roe Consulting PL	22.09.2021
39. Installation Certificate – Hydraulic Central Plumbing Contracting PL 40. + Installation Certificate (schedule of fire hazard properties – carpet and vinyl) + Certificate of Test No. FNR11455C + Product Data Sheet + Test Report No. 19-004615 + Homogeneous Vinyl Sheet + Test Report No. 7-566333-AN + Building Blocks – loop pile  41. Certificate of Test No. FNC11629 – stone wool 42. Reaction-to-fire test report no. RTF190172 – low carbon steel 43. Statement – Glue to insulated panel 44. External Wall system Disclosure Certificate 45. Test Report No. 16-002279 – colourbond steel 46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly 47. System Specifications – Steel Frame Internal Wall Systems 48. Installation Certificate – Schedule of Lightweight Fire Rated Construction 49. Installation Certificate – Warning & Operational signs 40. New Edge Group PL 41. Installation Certificate – Warning & Operational signs	37.	Structural Construction Certificate	Costin Roe Consulting PL	22.09.2021
40.	38.	Installation Certificate – Electrical	New Edge Group PL	25.11.2021
hazard properties – carpet and vinyl)  Certificate of Test No. FNR11455C  Product Data Sheet  Test Report No. 19-004615  Homogeneous Vinyl Sheet  Host Report No. 7-566333-AN  Building Blocks – loop pile  41. Certificate of Test No. FNC11629 – stone wool  ASKIN Engineering  ASKIN Engineering  O4.04  ASK	39.	Installation Certificate – Hydraulic	Central Plumbing Contracting PL	26.11.2021
42. Reaction-to-fire test report no. RTF190172 – low carbon steel  43. Statement – Glue to insulated panel ASKIN Engineering 04.04  44. External Wall system Disclosure Certificate Skyview Roofing 24.11  45. Test Report No. 16-002279 – colourbond steel AWTA Product Testing 10.05  46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly Branz 10.01  47. System Specifications – Steel Frame Internal Wall Systems Not Specified Not Specified Not Sull Systems Installation Certificate – Schedule of Lightweight Fire Rated Construction Australian Passive Fire 25.11  50. Architectural Performance Solution Report SBA Architects PL 09.09  51. Installation Certificate – Warning & Operational signs		hazard properties – carpet and vinyl)  + Certificate of Test No. FNR11455C  + Product Data Sheet  + Test Report No. 19-004615  + Homogeneous Vinyl Sheet  + Test Report No. 7-566333-AN	CSIRO Regupol AWTA Product Testing Armstrong Flooring Commercial AWTA Product Testing	13.08.2015 21.09.2015 25.10.2019 April 2017 13.05.2009 19.08.2021
42.Reaction-to-fire test report no. RTF190172 – low carbon steelWarringtonfire06.0843.Statement – Glue to insulated panelASKIN Engineering04.0444.External Wall system Disclosure CertificateSkyview Roofing24.1145.Test Report No. 16-002279 – colourbond steelAWTA Product Testing10.0546.Fire Assessment Report No. FC11160-001 – duct and fire damper assemblyBranz10.0147.System Specifications – Steel Frame Internal Wall SystemsNot SpecifiedNot S48.Installation Certificate – Schedule of Lightweight Fire Rated ConstructionInner Part Interiors03.1249.Installation Certificate – Fire SealsAustralian Passive Fire25.1150.Architectural Performance Solution ReportSBA Architects PL09.0951.Installation Certificate – Warning & Operational signsNew Edge Group PL25.11	41.	Certificate of Test No. FNC11629 – stone wool	CSIRO	04.02.2016
44.External Wall system Disclosure CertificateSkyview Roofing24.1145.Test Report No. 16-002279 – colourbond steelAWTA Product Testing10.0546.Fire Assessment Report No. FC11160-001 – duct and fire damper assemblyBranz10.0147.System Specifications – Steel Frame Internal Wall SystemsNot SpecifiedNot Specified48.Installation Certificate – Schedule of Lightweight Fire Rated ConstructionInner Part Interiors03.1249.Installation Certificate – Fire SealsAustralian Passive Fire25.1150.Architectural Performance Solution ReportSBA Architects PL09.0951.Installation Certificate – Warning & Operational signsNew Edge Group PL25.11			Warringtonfire	06.08.2019
45. Test Report No. 16-002279 – colourbond steel AWTA Product Testing 10.05 46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly 10.01 47. System Specifications – Steel Frame Internal Wall Systems Not Specified Not Specified Not Specified Using Systems Installation Certificate – Schedule of Lightweight Fire Rated Construction Inner Part Interiors 03.12 49. Installation Certificate – Fire Seals Australian Passive Fire 25.11 50. Architectural Performance Solution Report SBA Architects PL 09.09 51. Installation Certificate – Warning & Operational signs	43.	Statement – Glue to insulated panel	ASKIN Engineering	04.04.2018
45. Test Report No. 16-002279 – colourbond steel AWTA Product Testing 10.05 46. Fire Assessment Report No. FC11160-001 – duct and fire damper assembly 10.01 47. System Specifications – Steel Frame Internal Wall Systems Not Specified Not Specified Not Specified University Fire Rated Construction 103.12 48. Installation Certificate – Schedule of Lightweight Fire Rated Construction 103.12 49. Installation Certificate – Fire Seals Australian Passive Fire 25.11 50. Architectural Performance Solution Report SBA Architects PL 09.09 51. Installation Certificate – Warning & Operational signs New Edge Group PL 25.11	44.	·	-	24.11.2021
duct and fire damper assembly  47. System Specifications – Steel Frame Internal Wall Systems  48. Installation Certificate – Schedule of Lightweight Fire Rated Construction  49. Installation Certificate – Fire Seals Australian Passive Fire 25.11  50. Architectural Performance Solution Report SBA Architects PL 09.09  51. Installation Certificate – Warning & Operational signs	45.	Test Report No. 16-002279 – colourbond steel	AWTA Product Testing	10.05.2016
Wall Systems  48. Installation Certificate – Schedule of Lightweight Fire Rated Construction  49. Installation Certificate – Fire Seals  50. Architectural Performance Solution Report  51. Installation Certificate – Warning & Operational signs  Seals  Australian Passive Fire  25.11  Onumber 1  New Edge Group PL  25.11	46.		Branz	10.01.2019
Lightweight Fire Rated Construction  49. Installation Certificate – Fire Seals Australian Passive Fire 25.11  50. Architectural Performance Solution Report SBA Architects PL 09.09  51. Installation Certificate – Warning & Operational signs  New Edge Group PL 25.11	47.		Not Specified	Not Specified
50.       Architectural Performance Solution Report       SBA Architects PL       09.09         51.       Installation Certificate – Warning & Operational signs       New Edge Group PL       25.11	48.		Inner Part Interiors	03.12.2021
51. Installation Certificate – Warning & Operational signs  New Edge Group PL  25.11	49.	Installation Certificate – Fire Seals	Australian Passive Fire	25.11.2021
signs	50.	Architectural Performance Solution Report	SBA Architects PL	09.09.2021
52. Installation Certificate – Emergency Evacuation New Edge Group PL 25.11	51.		New Edge Group PL	25.11.2021
Lighting & Exits	52.	Installation Certificate – Emergency Evacuation Lighting & Exits	New Edge Group PL	25.11.2021
53. Installation Certificate – Required Exit Doors New Edge Group PL 25.11	53.	Installation Certificate – Required Exit Doors	New Edge Group PL	25.11.2021



Ітем	DOCUMENTATION	PREPARED BY	DATE
54.	Installation Certificate – Mirrors	Badel Kitchens	26.08.2021
55.	Installation Certificate – Windows	Alclad Architectural PL	03.08.2021
56.	Installation Certificate – Internal glazing	Alclad Architectural PL	03.08.2021
57.	Builders Compliance Certification	Qanstruct (Aust) PL	10.12.2021
58.	Installation Certificate – Windows	Alclad Architectural PL	03.08.2021
59.	Proactive Safety Design Certificate	Proactive Safety PL	23.06.2021
60.	Letter of Compliance – Roofing Materials	Skyview Roofing Australia PL	24.11.2021
61.	GLA Survey Plan	Real Serve	15.11.2021
62.	Certificate of Installation - Fencing	Summit Fencing	07.12.2021
63.	Acoustic Compliance Testing	RWDI Australia PL	29.11.2021
64.	Operational Environmental Management Plan	NSW Government Planning, Industry & Environment	06.12.2021
65.	Final Certification – Conveyor Support Platforms	Abbot Design (Aust) PL	28.10.2021
66.	Statement of Compliance – Conveyor Support Platforms	APC	28.10.2021
67.	Slip Test Report TCC21007-S07 Green mile concrete	The Coatings Consultancy PL	05.12.2021
68.	Mechanical Statement of Installation Compliance	Fredon Air PL	26.11.2021
69.	Inspection Certificate – Stormwater Retention Tank	Kneebone, Beretta & Hall PL	03.05.2021
70.	Mechanical Statement of Installation Compliance (1)	Fredon Air PL	26.11.2021
71.	Fire Assessment Report No. FC11812-001 - Nullifire	Branz	04.06.2020
72.	Installation Certificate – Schedule of Lightweight Construction	Inner Part Interiors	26.08.2021
73.	Installation Certificate – Fire Hydrants & Fire Hose Reels	Central Plumbing	26.11.2021
74.	Installation Certificate – Fire Shutters	Thompsons Roller Shutter PL	26.11.2021
75.	Installation Certificate – Fire Services  + Alarm Signalling Equipment + Automatic Fail Safe Devices + Automatic Fire Detection & Alarm System + Building Occupant Warning System activated by the Sprinkler System + Exit Signs (fire trip only) + Portable Fire Extinguishers	Force Fire & Safety PL	01.12.2021
76.	Installation Certificate – Insulated Sandwich Panels	Skyview Roofing Aust PL	24.11.2021
77.	Fire Trip Witness Statement	Chubb Fire & Security PL	07.12.2021
78.	Installation Certificate – Fire Control Centre	Qanstruct (Aust) PL	06.12.2021
79.	Installation Certificate – Lift Slip Resistance	Prestige Tiling Australia PL	30.11.2021
80.	Lift Registration	NSW Government SafeWork BSW	06.12.2021
81.	Surveyors Report	Real Serve	02.12.2021
82.	Installation Certificate – Waterproofing	Prestige Tiling Australia PL	25.11.2021
83.	Slip Test Report TCC21007-S02 Bump-outs Polished Sealed Concrete	The Coatings Consultancy PL	05.12.2021



İTEM	DOCUMENTATION	PREPARED BY	DATE
84.	Slip Test Report TCC21007-S03 Front Offices Polished Sealed Concrete	The Coatings Consultancy PL	05.12.2021
85.	Slip Test Report TCC21007-S04 Front Offices Exterior Concrete	The Coatings Consultancy PL	05.12.2021
86.	Builder Compliance Certification	Qanstruct (Aust) PL	30.11.2021
87.	Installation Certificate – Access for people with disabilities	Walmay Architectural Products PL	23.07.2021
88.	Fire Doorset Installation Certificate + Schedule	Inner Part Interiors	25.11.2021
89.	Builder Installation Statement – New façade and roof works	Qanstruct (Aust) PL	30.11.2021
90.	Slip Test Report TCC21007-S05 Front Offices Exterior Pavers	The Coatings Consultancy PL	05.12.2021
91.	Slip Test Report TCC21007-S06 Mezzanines	The Coatings Consultancy PL	05.12.2021
92.	Landscape Completion Certificate	Scape Design	15.12.2021
93.	Operational Environmental Management Plan	SLR Consulting Australia PL	30.11.2021
94.	Mezzanine Fire Hazard Properties	APC Storage Solutions	03.05.2021
95.	Slip Resistance Schedule (Mezzanine Flooring)	APC Storage Solutions	03.05.2021
96.	Slip Test Report MEX96A Interpon Griptex Yellow	Slipcheck	Not Specified
97.	Design Certification – Conveyor Support Platforms/Balustrades	Abbot Design (Aust) PL	07.12.2021
98.	Electrical Installation Certificate	Vanderlande	10.12.2021
99.	Contractor Contact List/Schedule (Fit-out)	Not Specified	Not Specified
100.	Regulatory Information report No. RIR 28418-03-metal pipe	Exova Warringtonfire	30.07.2018
101.	Landscape Implementation Certificate	Cabbagetree Landscape	16.12.2021
102.	Acoustic Certification	RWDI Australia PL	09.12.2021
103.	Section J Confirmation Letter	Sustainable Development Consultants	15.12.2021
104.	Installation Certificate - Lifts	Kleeman Elevators Australia	13.12.2021
105.	Letter - Waterproofing	Qanstruct (Aust) PL 16.12.2	
106.	Schedule of Floor Finishes:		
	+ Warranty/Installation	Sydney Bass Floor	21.09.2021
	+ Stone Initiatives Test No. SI-AWT- 2018	Regupol Australia PL CSIRO	29.08.2019 31.08.2015
	+ Test Report No. 7482	Armstrong	31.08.2015
	+ Slip Resistance	, amounding	01.00.2010
107.	Letter/Report Out – Final Fire Safety Report	FRNSW 17.12.2	
108.	Civil WAE Plans	CitiSurv PL	14.12.2021
109.	Structural Certification	Costin Roe Consulting	22.09.2021
110.	Fire Alarm Connection Notice	ADT Fire Monitoring	14.12.2021
111.	Commissioning Test Sheet - Diesel Sprinkler Tank (2)	Prime Pumps	29.10.2021
112.	Commissioning Test Sheet - Diesel Sprinkler Tank	Prime Pumps	10.12.2021
113.	Fire Resistant Doorset Schedule & Commissioning	Inner Part Interiors	02.12.2021
114.	Hose Reel Flow Test Sheet	City Pump Services Australia PL 03.12.	
115.	Hydrant Flow Test Sheet	City Pump Services Australia PL	03.12.2021



Irea	DOGUMENTATION	Donano Py	Date
ITEM 116	DOCUMENTATION  Sprinkler Flow Test Popults	PREPARED BY	<b>DATE</b>
116.	Sprinkler Flow Test Results	FPA Australia	10.12.2021
117.	Fire Assessment Report No. FC10266-001 - Fyrebox	Branz	04.08.2020
118.	Penetration Register-2D	Australian Passive Fire	03.09.2020
119.	Penetration Register-2D-Part-4	Australian Passive Fire	03.09.2020
120.	Penetration Register-Part-1	Australian Passive Fire	15.12.2021
121.	Penetration Register-Part-3 Electrical	Australian Passive Fire	05.11.2021
122.	Penetration Register-Part-5 Mechanical	Australian Passive Fire	11.06.2021
123.	Penetration Register-Part-6-2D	Australian Passive Fire	03.09.2020
124.	Penetration Register-Part-7 Plumbing	Australian Passive Fire	09.06.2021
125.	Penetration Register-Part-8-2D	Australian Passive Fire	03.09.2020
126.	Regulatory Information Report No. 27912900 - Hilti Fire stop	Warringtonfire	25.02.2020
127.	Regulatory Information Report No. FAS190248 - Firestop Block CFR_BL	Warringtonfire	09.10.2019
128.	OC Staging Plan	SBA Architects PL	13.03.2021
129.	Builders Compliance Certification	Qanstruct (Aust) PL	17.12.2021
130.	Fire Alarm System Commissioning	Force Fire	30.07.2021
131.	Regulatory Information Report RIR 25948-07 - Promaseal	Exova Warringtonfire	10.08.2017
132.	Fire Assessment Report No. FC12454-001 – Cable Transits	Branz	14.12.2020
133.	Regulatory Information Report No. FAS190234  – TBA Firefly	Warringtonfire	18.09.2020
134.	Regulatory Information Report No. FAS190235 – TBA Firefly	Warringtonfire	18.09.2020
135.	Assessment Report 29592300 - Promat Fire collars	Warringtonfire	21.06.2019
136.	Regulatory Information Report RIR C191611a.2 - UniCollars	Exova Warringtonfire	22.06.2020
137.	Fire Resistance Test Report No. WFRA F91754  – Cable penetrations	Warrington Fire Research	01.04.1999
138.	Technical Data Sheet - BOSS Cable Transits	Boss Passive Fire	April 2020
139.	Regulatory Information Report FAS190236 RIR1.0 – TBA Firefly	Warringtonfire	18.09.2020
140.	Assessment Report No. FCO-1579- Fyreflex sealant	CSIRO	04.06.2020
141.	System Certificate No. 1103 – FC Retrofit Collars	Promat Australia PL	Not Dated
142.	Technical Data Sheet -3-4 Hour Penetration Systems	Trafalgar Fire	Not Dated
143.	Installation Certificate – Emergency Management Plan	Pre-Empt PL	16.12.2021
144.	Installation Certificate Insulated Sandwich Panels	Skyview Roofing Australia PL	24.11.2021
145.	Installation Certificate Insulated Sandwich Panels	Askin Performance Panels PL	15.12.2021
146.	Accessibility Occupancy Certification	Morris Goding Access Consulting	17.12.2021
147.	Design Certification – Height Safety Fall Protection Systems	Sayfa Systems	17.12.2021



ITEM	DOCUMENTATION	PREPARED BY	DATE
148.	Height Safety Practical Completion Report	Access Compliance Services	17.12.2021
149.	Inspection and Test Record Pipework Pressure Test Reports	Force Fire PL	05.07.2021
150.	Installation Certificate – Civil & Stormwater	AT&L	20.12.2021
151.	Installation Certificate – Civil, Traffic, Carpark	AT&L	20.12.2021
152.	Balustrades and Facade Gates Certificate	Costin Roe Consulting	20.12.2021
153.	Builders Compliance Certificate – Blockwork Wall (Northern LV Room)	Qanstruct (Aust) PL	20.12.2021
154.	Fire Damper Register + Test Reports	Fredon	17.12.2021
155.	Certification of Performance Based Design Works	Innova Services	20.12.2021
156.	Supplementary Certification for Balustrades	Qanstruct (Aust) PL	20.12.2021
157.	FFSR Response Letter + Assoc. Commissioning Reports	Qanstruct (Aust) PL	18.12.2021
158.	Balustrades and Façade Gates Certification	Costin Roe Consulting	20.12.2021

## EP&A AMENDMENT (FIRE SAFETY & BUILDING CERTIFICATION) REGULATION 2017 (cl. 155(1)(f))

Documentation relied upon as required by the Environment Planning & Assessment Amendment (Fire Safety & Building Certification) Regulation 2017:

+ Proposed Alternative Solution Reports in respect of a fire safety requirement:

TITLE OF REPORT: Fire Engineering Report

**DATE OF REPORT:** 30.07.2021

REFERENCE NO. & VERSION: 19378-R01 Rev 8

NAME OF FIRE SAFETY ENGINEER: Jason Powell

ACCREDITATION NO.: BDC0801



## **SCHEDULE 2**

## FIRE SAFETY SCHEDULE

Issued under Clause 168 of the Environmental Planning & Assessment Regulation 2000

Owner: BGMG 11 Pty Ltd

Address: 2 Aldington Road, Kemps Creek NSW 2178

**DEVELOPMENT APPLICATION NO.:** SSD 10397 & SSD 7348

CONSTRUCTION CERTIFICATE NO.: CC-20105, CC-20130, CC-20139, CC-20161, CC-21003/A & CC-21003/B

OCCUPATION CERTIFICATE No.: OC-21139

## SCHEDULE

Statutory Fire Safety Measure	Design / Installation Standard	Existing
Alarm Signalling Equipment	AS 1670.3 – 2018	✓
Automatic Fail Safe Devices	BCA Clause D2.21	✓
Automatic Fire Detection & Alarm System	BCA Spec. E2.2a & AS 1670.1 – 2018 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	<b>√</b>
Automatic Fire Suppression Systems	BCA Spec. E1.5 & AS 2118.1 – 2017 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	✓
Building Occupant Warning System activated by the Sprinkler System	BCA Spec. E1.5, Clause 8 and Clause 3.22 of AS 1670.1 – 2018	✓
Emergency Lighting	BCA Clause E4.4 & AS 2293.1 – 2018	✓
Emergency Management Plan	AS 3745-2010 and Fire Safety Engineering Report prepared by Innova Services, Report No. 19378-R01, Revision 8, dated 30.07.2021	
Exit Signs (including Dynamic Exit Signs)	BCA Clauses E4.5, E4.6 & E4.8; and AS 2293.1 – 2018 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	<b>√</b>
Fire Control Centre	BCA Spec E1.8	
Fire Doors	BCA Clause C2.12, C2.13, C3.5, C3.8; and AS 1905.1 – 2015 and manufacturer's specification, and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	<b>√</b>
Fire Hose Reels	BCA Clause E1.4 & AS 2441 – 2005 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	<b>√</b>
Fire Hydrant Systems	Clause E1.3 & AS 2419.1 – 2005 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	<b>√</b>
Fire Seals	BCA Clause C3.15, AS 1530.4 – 2014 & AS 4072.1 – 2005 and manufacturer's specification	✓
Fire Shutters	AS 1905.1-2005 and Fire Safety Engineering Report prepared by Innova Services, 19378-R01, Report No 19378-R01, Revision 8, dated 30.07.2021	<b>√</b>
Insulated Sandwich Panels	IPCA Code of Practice 2017 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	
Mechanical Air Handling Systems	BCA Clause E2.2, AS/NZS 1668.1 – 2015 & AS 1668.2 – 2012 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	✓



Statutory Fire Safety Measure	Design / Installation Standard	Existing
Paths of Travel	EP&A Regulation Clause 186 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	✓
Perimeter Vehicular Access	BCA Clause C2.4 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	✓
Portable Fire Extinguishers	BCA Clause E1.6 & AS 2444 – 2001	✓
Required Exit Doors (power operated)	BCA Clause D2.19(b)	✓
Smoke Hazard Management Systems – Smoke Exhaust	BCA Part E2, Spec. E2.2b& AS/NZS 1668.1 –2015 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	✓
Warning & Operational Signs	Section 183 of the EP&A Regulation 2000, AS 1905.1 – 2015, BCA Clause D2.23, D3.6, E3.3 and Fire Safety Engineering Report prepared by Innova Services, Report No 19378-R01, Revision 8, dated 30.07.2021	<b>√</b>
Fire engineered Alternative Solutions relating to:  + Perimeter Vehicular Access limitations  + Fire Resistance Levels – Tensile Membrane Action  + Fire Resistance – Omission of fire rating to Ground Floor Office and Mezzanine  + Vertical separation of shafts  + Fire Resisting Construction-Support of another part  + Fire Resistance Levels-Rationalisation of Fire Resistance to Sanitary Facilities/Break-Out Rooms  + Exposure between Fire Compartments  + Width of Egress Travel Path  + Discharge from Fire Isolated Stairs into Main Entry Lobby  + Extended Egress Distances and Rationalised Smoke Hazard Management design  + Fire Hydrant System design, including booster location, x3 lengths of hose for coverage and external hydrants under awnings & Sprinkler Booster location  + Deletion of Fire Hose Reels to the Level 1-3 Robotics Fields and use of 50m Hose Reels in all other areas  + Deletion of Directional Emergency Exit Signage to the Level 1-3 Robotics Fields  + The rapid roller doors protecting the dock doors have not been tested to comply with Table 4 of Specification C1.10.  + Building elements that require a fire rating of 240 minutes for integrity and insultation will be protected by systems that achieve a time grading of not less than 120 minutes for integrity and insultation will be rotected by systems that achieve a time grading of not less than 120 minutes for integrity and insultation.  + Permit the use of construction joints between various fire rated systems that are not in accordance with a tested prototype.  + Building identification signage is constructed of backing material that has not been directly tested to achieve a Group Number 1 or 2.	BCA Performance Requirements CP1, CP2, CP4, CP8, CP9, DP4, DP5, DP6, EP1.1, EP1.3, EP1.4, EP2.2 & EP4.2, Fire Safety Engineering Report prepared by Innova Services, Report No. 19378-R01, Revision 8, dated 30.07.2021	
Performance Solution relating to:  + Maintenance area path height clearances	BCA Performance Requirements DP6 & FP3.1, Performance Based Design Report prepared by Innova Services, Report No. 19378-R03, Revision 2, dated 19.11.2021	<b>√</b>



# **SCHEDULE 3**

#### INSPECTION SCHEDULE

Inspection Type		Inspection by	Date	Satisfactory
•	After excavation for, and before the placement of, any footings	Dean Goldsmith (BDC0141)	29.06.2020	Yes
•	Prior to covering any stormwater drainage connections.	Dean Goldsmith (BDC0141)	29.06.2020	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	19.01.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	12.03.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	24.03.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	07.04.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	28.04.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	16.06.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	04.08.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	08.09.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	22.09.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	29.09.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	06.10.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	03.11.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	10.11.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	17.11.2021	Yes
•	Progress Inspection	Dean Goldsmith (BDC0141)	24.11.2021	Yes
•	Progress Inspection & Fire Systems Testing	Dean Goldsmith (BDC0141)	01.12.2021	Yes
•	Progress Inspection & Witness Testing (Level 1)	Dean Goldsmith (BDC0141)	08.12.2021	Yes
•	Progress Inspection & Witness Testing (Level 2)	Dean Goldsmith (BDC0141)	15.12.2021	Yes
•	Progress Inspection and FRNSW CI.152 FFSR Inspection	Dean Goldsmith (BDC0141)	16.12.2021	Yes
•	After the building work has been completed and prior to any occupation certificate being issued in relation to the building (OC1).	Dean Goldsmith (BDC0141)	20.12.2021	Yes



20 December 2021

The General Manager Penrith City Council PO Box 60 PENRITH NSW 2751

Dear Sir / Madam,

REFERENCE: DA NO. SSD 10397 & SSD 7348

2-18 ALDINGTON ROAD, KEMPS CREEK (OAKDALE WEST ESTATE)

OCCUPATION CERTIFICATE

As required by Clause 151(2) of the EP&A Regulation 2000 (the Regulation) notice is hereby given that the following application for Occupation Certificate has now been approved.

Applicant: Goodman Property Services (Aust) PL

Subject Address: 2 Aldington Road, Kemps Creek

Project No: 200139

Date Received: 20 December 2021

Date Determined: 20 December 2021

Please find undercover a copy of the Occupation Certificate No. OC-21139 for the completed Stage 2 development including construction, subdivision, fit-out, operation and use of a four-level automated warehouse, associated office space, internal roads and parking, excluding the Level 3 (P4) automation equipment fitout and the operation of the P4 AR field.

We have also submitted a copy of the documentation relied upon as indicated on the Occupation Certificate via the ePlanning Portal for Council's record.

Pursuant to Clause 263(2) Environmental Planning and Assessment Regulation 2000, please note that payment has been made via the NSW ePlanning Portal to the sum of \$41.00 for the submission of this Part 6 Certificate.

Please contact the undersigned should you have any further enquiries on 02 9211 7777.

Yours sincerely,

Dean Goldsmith

Director

Blackett Maguire + Goldsmith Pty Ltd

Contact Ph: 02 9211 7777 Fax: 02 9211 7774

Email: admin@bmplusg.com.au