ENVIRONMENTAL CONSULTANT MANAGEMENT REPORT SSD 10397 - Oakdale West Industrial Estate (OWE): Lot 2B For the period 1 FEB 2020 to 28 FEB 2021 (ECMR 9)



ErSed Ref: 19007-ECMR-9-1-210315

1.	Construction activities	Works at the site to the end of the reporting period were:					
1.	carried out during the						
	reporting period	 Concreting – Footings & Columns Concrete slab pours – Levels Ground (internal & external), levels 1, 2 & 3 					
		Stormwater and drainage installation Structural Structura					
		Structural Steel erection					
		Structural Fire Protection					
		Roof installation					
		Steel fixing					
		External wall cladding					
		Plumbing					
		Pre-Cast Panel Installation					
		Glazing / Windows Installation					
		Electrical temporary works					
		Loading Docks					
		Fire Services					
		Syphonic Drainage					
		Painting					
		Mechanical including roof unit installation					
		Blockwork					
		Landscaping					
		Mezzanine Floor – Internal Steelwork					
		Acoustic Panelling					
		Internal Fit Out – Gyprock Walls and services					
		Roller Doors					
		High Voltage Electrical					
		Stairway fit out – handrails					
2.	Proposed upcoming	Projected works for the next month are:					
	construction works (where	Concrete slab pours – Levels Ground internal and external					
	known)	Stormwater and drainage installation					
		Structural Steel erection					
		Structural Fire Protection					
		Excavation & Concrete work for office footings					
		Roof installation					
		Steel fixing					
		External wall cladding					
		Plumbing					
		Pre-Cast Panel Installation					
		Glazing / Windows Installation					
		0.0267					
		Flectrical works					
		Electrical works Loading Docks					
		Loading Docks					
		Loading DocksFire Services					
		Loading DocksFire ServicesSyphonic Drainage					
		 Loading Docks Fire Services Syphonic Drainage Painting 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation Landscaping 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation Landscaping Mezzanine Floor – Internal Steelwork 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation Landscaping Mezzanine Floor – Internal Steelwork Acoustic Panelling 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation Landscaping Mezzanine Floor – Internal Steelwork Acoustic Panelling Internal Fit Out – Gyprock Walls and services 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation Landscaping Mezzanine Floor – Internal Steelwork Acoustic Panelling Internal Fit Out – Gyprock Walls and services Roller Doors 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation Landscaping Mezzanine Floor – Internal Steelwork Acoustic Panelling Internal Fit Out – Gyprock Walls and services Roller Doors Flooring 					
		 Loading Docks Fire Services Syphonic Drainage Painting Mechanical including roof unit installation Landscaping Mezzanine Floor – Internal Steelwork Acoustic Panelling Internal Fit Out – Gyprock Walls and services Roller Doors 					

		Car Park works						
		High Voltage Electrical						
		Telecommunications						
3.	EC activities undertaken during	this reporting period						
	Site inspections	The EC has undertaken the following inspections;						
		5 FEB 21						
	<u>Audits undertaken</u>	The following Audits were undertaken in the period.						
		NIL						
4.	Summary of Community Consultation	The CCS includes the register of consultation and communication for the Project. A summarised extract for the period is provided as Attachment 1. Complete records of the register are available if required.						
5.	Summary of Complaints	The following complaints have been received during the period.						
		Resident 141 Aldington Road Resident advised that the road was damaged at the front of his property. SLR advised Goodman who provided advice to the resident that contractor would inspect damage and advise on rectification required. Resolution Contractor inspected damage and determined repairs were required and these have been completed.						
6.	Summary of Incidents	The following incidents have been reported during the period.						
		NIL						
7.	Summary of Non – Compliances	The following non compliances have been received during the period.						
8.	Summary of Noise monitoring	Condition B28 requires that: The environmental representative for the OWE must review and provide the results of noise monitoring to the Planning Secretary on request, including details of the measures taken to minimise noise to ensure compliance with the noise goals. Noise data for the reporting period obtained by the western monitoring station was provided to the environmental representative for the OWE. This station will monitor noise levels from both SSD7348 (OWE) and SSD 10397 (Lot 2B). No exceedance or near exceedance "red alerts" for noise were received for FEB 2021 which were attributable to the Development.						
9.	Evaluation of Environmental Performance	Works have been accordance with the approved management plans and the Conditions of Approval.						
10.	Analysis of Lesson Learnt and Opportunities for improvement	NIL						
11.	Any changes to the project including changes to CEMP and other Project Documentation	NIL						
12.	Any meetings attended by EC	The EC has been involved in the following meetings; 05/02/21 Virtual teams meeting to discuss findings of Audit 17 DEC 20 and response / implementation						

13.	Summary of documents issued by the EC	The following documents were issued by the EC.
		15/02/21 19007 ECMR -08-210215 Environmental Consultant Monthly Report for JAN 21
14.	Closing Remarks	NIL

Attachment 1 – Extract of Consultation and Communication Register

Date	Responsible Rep	In/Out/ Meeting	Initial Communication Method/Tool	Contact Name/Organisation	Nature of Complaint/Enquiry/ Communication	Summary of Issues/Details of Communication	Resolution
10.02.21	Kate McKinnon	Meeting	meeting	DPIE, TfNSW, WaterNSW, Sydney Water, Goodman), ErSed, AT&L, SLR Consulting	Agency Consultation Meeting	Scheduled Consultation Meeting and targeted consultation re staging plan and 1B/1C CEMP. Undertaken virtually via Microsoft Teams	Minutes recorded and circulated to all those invited
10.02.21	Kate McKinnon	Meeting	meeting	Trinity Primary School, Fitzpatrick Investments, Goodman ErSed, SLR Consulting	Community Consultation Meeting	Scheduled Consultation Meeting undertaken virtually via Microsoft Teams	Minutes recorded and circulated to all those invited
12.02.21	Kate McKinnon	In	Phone	Resident 141 Aldington Road	Repairs required to Aldington Road	Call received from resident advising road was damaged at the front of his property in locations that were not covered by previous repair works. SLR advised they would pass this information onto Goodman and provide update ASAP on proposed actions. Goodman provided advice that contractor would inspect damage and advise on rectification required. This information was provided to the resident via text message.	Contractor inspected damage and determined repairs to be made with confirmation of completion provided to resident.
23.02.21	Kate McKinnon	Out	email	Trinity Primary School, Fitzpatrick Investments, Goodman, ErSed, SLR Consulting	Distribution of Meeting Minutes and Presentation	Email sent to all attendees of the 10.02.21 Community meeting with finalised copy of minutes and of copy of presentation	Email sent via BCC

Date	Responsible Rep	In/Out/ Meeting	Initial Communication Method/Tool	Contact Name/Organisation	Nature of Complaint/Enquiry/Communication	Summary of Issues/Details of Communication	Resolution
23.02.21	Kate McKinnon	Out	email	DPIE, TfNSW, WaterNSW, Sydney Water, Goodman), ErSed, AT&L, SLR Consulting	Distribution of Meeting Minutes and Presentation	Email sent to all attendees of the 10.02.21 Agency meeting with finalised copy of minutes and of copy of presentation	Email sent via BCC
24.02.21	Kate McKinnon	Out	email	DPIE, TfNSW, WaterNSW, Sydney Water, Goodman), ErSed AT&L SLR Consulting	Revision, presentation resent in PDF version	Revision sent, attaching PDF version of presentation for ease of review	Email sent via BCC
24.02.21	Kate McKinnon	In	email	Emmaus Village, Emmaus College	Correspondence between external parties Re creek downstream of bridge	Correspondence between parties was received raising issue with the overgrown state of the downstream creek from a bridge within the site neighbouring the project site and comments made by ground staff of the School to a resident of the village. Spoke with Rosemary and confirmed this was not related to the project however she wanted Goodman to be aware of the matter	No action - does not relate to project

Date	Responsible Rep	In/Out/ Meeting	Initial Communication Method/Tool	Contact Name/Organisation	Nature of Complaint/Enquiry/ Communication	Summary of Issues/Details of Communication	Resolution
26.02.21	Kym Dracopoulos	In	phone	Resident 20 Aldington Road	Discussion of upcoming DAs, dog fence and dust	Discussion held with resident about details of upcoming Council D.A.s. Discussion regarding measures to keep his dog on his property - Goodman advised they would provide temporary fencing. Discussed dust on residents roof, agreed to complete a roof cleaning once works are complete	Record of conversation provided to CCLR